

# Rangemaster Thunder 2009 Quick Installation Guide

## Sample configuration for TRAP FO - 15 machines

Rangemaster Thunder 2009 Sequencer with 110/220VAC power-supply

Rangemaster Thunder 2009 Sequencer mit 110/220V Wechselstrom-Anschluß




1,5m cable to Thunder Sequencer  
1,5m Verbindungskabel zu Sequencer

1,5 m cable to Thunder Sequencer  
1,5 m Verbindungskabel zu Sequencer



Mikrophone connector board  
Mikrophon-Anschlußplatine



Interface box for  
Skeet/Sporting/Trap  
Internal power supply  
Interne Stromversorgung  
12VDC/24VDC  
5V/12V/24V Status LEDs  
Skeet/Sporting/Buzzer Board  
Trap board

Cable/Kabel: 3x0,75mm<sup>2</sup>



Microphon Station 1

Station 2

Station 3

Station 4

Station 5